



OSET

TECH BULLETIN

20.0 RELAY ISSUE

It has come to our attention that when a bike with a failed relay has come in for repair that the screws that mount the relay to the frame had been replaced with ones that are too long. This causes damage to the relay.

If you are fitting a relay and the screws have been lost please call OSET to acquire the correct screws.

All new relays purchased will be sent out *WITH* new screws.

REGARDS,
OSET TECH SUPPORT